

# Oil Field Environmental Incident Summary

**Incident:** 20150512162820      **Date/Time of Notice:** 05/12/2015 16:28  
**Responsible Party:** HRC OPERATING, LLC  
**Well Operator:** HRC OPERATING, LLC  
**Well Name:** MANGER 1 SWD  
**Field Name:** STRANDAHL      **Well File #:** 90211  
**Date Incident:** 5/11/2015      **Time Incident:** 10:00      **Facility ID Number:**  
**County:** WILLIAMS      **Twp:** 157      **Rng:** 103      **Sec:** 1      **Qtr:** SW SW  
**Location Description:** Spill was contained within secondary containment at the Manger SWD.

**Submitted By:** Julia Traster      **Received By:**

**Contact Person:** Chris Martinez  
1801 CALIFORNIA STREET  
SUITE 3500  
DENVER, CO 80202

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2600 Feet

**Distance Nearest Water Well:** 2600 Feet

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels	1	Barrels		
<b>Brine</b>					1	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 8/7/2015      **Clean Up Concluded:** 5/12/2015

**Risk Evaluation:**

Low health hazard,

**Areal Extent:**

**Potential Environmental Impacts:**

No impact to surface or ground water. Affected soil was removed and will be disposed of properly.

**Action Taken or Planned:**

Spill was contained within facility secondary containment. Standing liquid was picked up by trucks on location. Oil affected dirt was removed.

**Wastes Disposal Location:** All oily soil will be disposed of at an approved disposal location.

**Agencies Involved:****Updates**

---

**Date:** 5/13/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.